Ladybug VEE Power Meter Code

Overview

This document introduces the user to using Ladybug power sensors in a VEE environment. It assumes familiarity with VEE but does not require expertise. It demonstrates key functions including:

- Sensor Initialization
- Sensor Setup (Frequency, Averages, Measurement Units)
- CW Measurements
- Pulse Measurements
- Ratio Measurements

An example power meter application (with source code) is included. The user interface is shown in figure 1. It is designed to be easy to understand and uses many of the most common functions. It will work with one or more sensors.

Note: All VEE software is written in VEE 7.5.



Figure 1: VEE Power Meter Interface. Note that changes may be incorporated for cosmetic reasons or as new functionality is added. The interface may also change depending on some selections.

Exercising the VEE Power Meter Application

The VEE Power Meter is an interactive application designed to be similar to the front panel of more traditional power meters. Extra features, such as the plot, were added to emphasize some of the benefits of the Ladybug Sensor.

The software has many capabilities and is easy to use. A few of the settings and techniques are shown here to assist you in getting started.

Software Installation

To install the software, simply unzip all of the files in the appropriate folder. Note that all files should remain in the same folder. This is especially true of the .DLL and .H files. If you wish to create your own VEE application, the location of these files is critical.

Setting the Frequency

To set the frequency, change the value in the frequency control (shown below in yellow). You may also change the units (shown in red) as necessary. These changes will take effect immediately.

Note that this will only change the frequency for the active sensor. If more than one sensor is connected, the others will not change. If you are performing ratio measurements, the settings for Sensor A can be copied to Sensor B by pressing the Mirror Sensor button.



Figure 2: The frequency may be changed by any combination of the frequency value (shown in yellow) and the units (shown in red). Note that the Mirror Sensors button (shown in green) is only visible during ratio measurements.

Setting the Power Units

To set the power units, simply select the units from the drop-down list (shown in yellow). Note that the power units display shows the units for an individual sensor during ratio measurements.

೫ Agilent VEE Pro - Pov	ver Meter.vee					
<u>File Edit View Debug</u> Fl	ow <u>D</u> evice <u>S</u> ystem <u>I</u> /O	Data Display Excel Window Help				
■ ● ► ►	-∎∃∃₽	신 🗗 🛱 🧶 🗛 🐜 🛅 🎞 ル	X h l h n n l	73 W 🖪 🗗 🥸		
Measurement Pane	el					
	Averages	Trigger In	Extended	Averages	Exit	
C Anti Aliasing	75	Internal Continuous	1		Preset	
Limit Enabled		Trigger In Timeout	🗆 Ext Avg	j Enabled	Fiese	
Trinnen Out		0.5	Reset Ex	t Avaina	Reset Plot	
Trigger Out Pol	aritv				Mirror Sensors	
Trigger In Polar	ity				ID Sensor A	
Contraction Logging Enable	d				ID Sensor B	
Sensor A					Rst Max & XAvg	
LB479A	188 086188				Set Ref	
Sensor B					Single Meas	
LB479A	188 086188	3			Setup Limits	
					Change Logfile	
Power Level		Frequency		Measurement		
-20 074 🤇	dBm	-		CW	-	
20.014	ubiii		GHZ			
-20.07 dBm -20.07						
-20.07		t leik ut e				
-20.07	hatha it in the state					
-20.07		i na shi na shi ka shekara				
CW -20.07	· الشريع الأبر الأم ^ا				<u>.</u>	
-20.07 -20.07						
-20.07				The state of the s		
-20.08		4000	8000	12k	14k	
Auto Scale		Sample	9			
V — x: 89.99		y: -20	08			
🔺 — x: 89.99		y: -20	08			
<u>v⊥</u> x:0 y:0						
Log File: C	:\tmp.csv					

Figure 3: The power units control only controls sensor A. It also displays the current setting for Sensor A.

Making a CW Measurement

The default measurement when the system starts is CW. Generally speaking, this can be performed without any difficulty. To switch back to CW from another measurement, simply select CW from the drop-down list (shown below in yellow).

🐞 Agilent VEE Pro - Pow	er Meter.vee					[
<u>File Edit View Debug Flo</u>	w <u>D</u> evice <u>S</u> ystem <u>I</u> /O	Da <u>t</u> a Di <u>s</u> play E <u>x</u> cel <u>W</u> ind	ow <u>H</u> elp		1		
		🛯 🔁 🏛 🛤 🌑 🛤	Fra 8: 20 /2 X		ች 🕷 🖪 💣 🕸		
Measurement Panel							
	Averages	Trigger In		Extended	Averages	Exit	
Anti Aliasing	15	Internal Contin	nuous <u> </u>			Preset	
		n 5	ut	🗆 Ext Avg	j Enabled	Deset Dist	
Trigger Out		10.0		Reset Ex	t Avging	Reset FIOL	
Trigger Out Pola	arity					Mirror Senso	rs
🗆 Trigger In Polari	☐ Trigger In Polarity					ID Sensor A	
🗆 Logging Enable	d					ID Sensor B	
Sensor A						Rst Max & XA	vg
LB479A	188 086188					Set Ref	
Sensor B						Single Meas	
LB479A	188 086188					Setup Limite	
						Change Logri	
Power Level		Fre	quency		Measurement		
-20.074	dBm	• 1		GHz -	cw	•	>
-20.07							
dBm -20.07							
-20.07							
-20.07			halle to be had been		a), (a))		
-20.07 CW -20.07	<mark>ha dalah sa sa ku</mark> ngan kungan kung	in the second		lin da kalin da kini di k			
-20.07			a at a start a	H <mark>alan (</mark> alah) ^a ka			
-20.07 -20.07							
-20.08		4000		8000	124	14k	
Auto Scale		1000	Sample		.28		
×: 89.99			y: -20.08				
x: 89.99 y20.08							
0.2 0.2 0.2							
Log File: C	tmp.csv						

Figure 4: The default measurement type is CW. Measurements will be made continuously unless the Trigger In control (in green) is set to something other than "Internal Continuous".

Making a Pulse Measurement

Similarly, pulse measurements are made by selecting the Pulsed value from the dropdown list. Note that the additional quantities Duty Cycle, Peak Power, and Crest Factor (all shown in yellow) appear after this selection is made. Also, note that 5xx series sensors cannot make pulse measurements even though this option may be selected.

🗩 Agilent VEE Pro - Powe	r Meter.vee					
Elle Edit View Debug Flow Device System I/O Data Digolay Excel Window Help						
1 🖉 🖬 🚭 🕨 🕨	■ 	िक 🖬 लें 🌒 👫 🐜 🛅 🔍 /	X B B O O I	°a 🛪 🖪 💣 🕸		
Measurement Panel						
	Averages	Trigger In	Extended	Averages	Exit	
🗆 Anti Aliasing	75	Internal Continuous	1			
🗆 Limit Enabled		Trigger In Timeout	🗆 Ext Avg	Enabled	Preset	
🗆 Max Hold		0.5			Reset Plot	
Trigger Out				t Avging	Mirror Sensors	
Trigger Out Polar	Trigger Out Polarity				ID Sensor A	
	,					
Sensor A					LI Sensor B	
LB479A	188 086 <u>188</u>				Rst Max & XAvg	
					Set Ref	
Sensor B			Duty Cycle	100.000%	Single Meas	
LB479A	188 0 86188		Peak Power	-19.934 dBm	Setup Limits	
			Crest Factor	0.129 dB	Ohan na La afila	
Power Level		Frequency		Measurement		
-20.063	dBm 🔽	1	GHz 🔹	Pulse	d	
-20.06						
dBm 20.06			· · · · ·			
-20.06				واللع والمتعطية عن المتلكة والعد	ellengi -	
-20.06				اللاعة التعلقين ومراقلهم والالم	u _{dija.}	
-20.07			and the second second		-	
Pulsed 20.07		a sale da Ma				
-20.07	W. Margari				-	
-20.08			• •			
-20.08		10k	20k	30k	35k	
Auto Scale		Sampl	e			
y — x:89.99 y: 20.08						
→ x: 89.99 ▼→ x: 0	x 10					
Log File: C:)	tmp.csv					

Figure 5: The additional pulse measurements are shown on the right. The units for duty cycle are alway percent and the units for crest factor are always dB. The units for the other parameters are always the same as the power units (except for pulse ratio).

Making a Ratio Measurement

Ratio measurements are made by selecting either of the Ratio options (CW or pulsed). CW is shown here. Not surprisingly, ratio measurements require two sensors for the results to make sense.

The Again of the Dross Downer Meter wee						
Ref Agrication Design Flow Device System I/O Data Display Excel Window Help						
こば目母 ▶ ▶ Ⅱ ■ 舌 舌 台 也 邸 自 政 ● ▲ 塾 国 型 ル 氷 暫 臨 り マ 活 状 図 雪 ⊗						
Measurement Panel						
Averages	Trigger In	Extended Averages	Exit			
Anti Aliasing 75	Internal Continuous 🔹	1				
🗆 Limit Enabled	Trigger In Timeout	Ext Avg Enabled	Preset			
🗆 Max Hold	0.5		Reset Plot			
🗆 Trigger Out		Reset Ext Avging	Mirror Sensors			
Trigger Out Polarity						
Trigger In Polarity			ID Sensor A			
Logging Enabled			ID Sensor B			
Sensor A	_		Rst Max & XAvg			
LB579A 64 091320			Set Ref			
Sensor B			Single Meas			
LB479A 188 086188 LB579A 64 091320	_		Setup Limits			
			Change Logfile			
Power Level	Frequency	Measurement				
59.929 dBm	• 1	GHz · Ratio (C	W) -			
			·			
69 1 </td						
Ratio (CW) 45	<u>H Hanna an that Ma</u>	halladh Mil II. Alaidh M. A. A				
35 0	100	200	300			
Auto Scale	Sample					
V — x: 62.89	y: -20.08					
△ — x: 62.89	y: -20.08					
	y.0					
Log File: C:\tmp.csv						

Figure 6: Note that the ratio measurements are always A-B (or A/B for linear units). To display B-A, simply switch the selected sensors.

Using and Modifying the Code

Sensor Communication

Communication with LadyBug power sensors is done through the index, the serial number, or the address of the sensor. In this example code, all communication is done through the address. This is because the address covers more functionality than the others and because it makes the code more flexible. For example, the user cannot change the serial number of a sensor but they can change the address.

Library Setup

Since all calls to the power sensor are done with DLL function calls, the library must be imported prior to calling any of the routines. This is a fairly simple process with an example of the VEE code shown in the following figure.



Figure 7: The crucial setting for an imported library is setting the Library Type to "Compiled Function". It is also good practice to delete the library prior to importing it.

Initializing the Sensors

Before the sensors can be used, they must be initialized. The code performs additional steps as well, but we will focus on the steps necessary for any application. You may need the additional steps depending upon your application.

The first step in this process is to obtain the sensor list. This is followed by initializing each sensor. This initialization only needs to be done once.

In the power meter code, these steps are performed as shown in the following figures.



Figure 8: "Get Sensor List" userFunction. Note that the SensorList is an array of records.



Figure 9: "Initialize All Sensors" uses the address fields of each record in the array.

An easy way to initialize all sensors is shown below:



Figure 10: Easy Initialization example (Example 1.vee). This example may be found in the examples folder. Note that it does not include the library import.

Sensor Identification

To make the LED on the current power sensor blink several times, use the LB_BlinkLED_Addr function.



Figure 11: This function is used to physically identify the sensor at the given address.

Setting the Frequency

To set the power sensor frequency, use the LB_Set_Frequency function. Note that the frequency must be in Hertz. You will need to account for this before calling this function (as was done in the power meter code).



Figure 12: With these parameters, the power sensor at address A would be set to the frequency of the Freq pin.

Setting the Power Units

To set the power units, use the LB_SetMeasurementPowerUnits function as shown in the figure. Possible units include dBm, dBW, dBkW, dBuV, dBmV, dBV, Watts, Volts, and dB Relative.



Figure 13: With these parameters, the LB_SetMeasurementPowerUnits will set the power sensor to dBm. Note that the ordinal output of the radio button control is used (not the enum). Also, the order of the units in the radio buttons control is critical.

Making a CW Measurement

The Get CW Measurement (Address).vee example will measure the CW power for the sensor at the given address in the selected units of the sensor. This example shows the minimum required to make this measurement, including importing the library, initializing the sensor, setting the frequency, setting the power units, and making the measurements.



Figure 14: The CW Measurement Example shows how to take continuous CW measurements. Note that the address (188) will probably have to be modified for your needs.

Making a Pulse Measurement

Similarly, the Get Pulse Measurement.vee example will measure the pulse power for the selected sensor.



Figure 15: The Pulse Measurement example is similar in format to the CW Measurement example but note that it has four outputs.

Making a Ratio Measurement

Ratio measurements simply involve setting up and measuring power levels from two sensors. There is no single function that performs this measurement.

The Ratio Measurement.vee example demonstrates how to perform these measurements. Note that ratio measurements are subtracted for logarithmic units (such as dBm) and divided for linear units.



Figure 16: This example shows a CW ratio measurement of two sensors at 1 GHz. Note that units are treated differently in ratio measurements.

Adding to Existing Projects

The VEE files distributed with this code can be added directly to any existing project. It is recommended that you check to ensure that the DLL functions are imported correctly at the beginning of the program. This may require modification to the folders specified by the import DLL function.