


Quick Start Card - Windows 7 only

V4.5 LBXXXA Series USB PowerSensor+™


Power Meter and Pulse Profiling Applications Software Install

NOTE: Installing .NET Framework 4.0 from the LB Flash Drive




If this error appears, it means that the required .Net 4.0 Framework is not installed on your computer. A full install of .NET 4.0 is available on your flash drive.

Run "dotNetFx40_Full_x86_x64.exe" from the flash drive root directory. When .NET Setup window appears, select "Install". Return to Step 2.




1



Insert
Flash
Drive

2


Open folder,
run Setup.exe
from the root
directory of the
flash drive.



Note: if a .NET framework error appears after running Setup.exe, go the last page for instructions.

3

Select
"Yes" and
"Next"



4



< Click Next




©LadyBug Technologies LLC 2005-2011
www.ladybug-tech.com

5




< Click Next

6



< Check Both PM & PPA for Pulse Profiling, Check only Power Meter App for non-Pulse Profile sensors
< Check High Speed Logger and/or Sample Code if desired

7




^ Click Next for both

8



^ Click Next

9




^ Select Install

10



^ Select Finish, then Close

11



Connect Sensor

12



Installation Complete.
Begin Making Power Measurements ... 