


Quick Start Card - Windows XP only




V4.5 LBXXXA Series USB PowerSensor+™
Power Meter and Pulse Profiling Applications Software Install

NOTE: Installing .NET Framework 4.0 from the LB Flash Drive




If this error appears, it means that the required .Net 4.0 Framework is not installed on your computer. A full install of .NET 4.0 is available on your flash drive.

Run "dotNetFx40_Full_x86_x64.exe" from the flash drive root directory. When .NET Setup window appears, select "Install". Select "Finish" when completed. Return to Step 2.




1



Insert
Flash
Drive

2



If the flash drive root directory does not open, then open the LB flash drive root directory and run "Setup.exe"

Note: if a .NET Framework error appears after running Setup.exe, go to the last page for instructions.

3



← Click Next

4



← Click Next



©LadyBug Technologies LLC 2005-2011


www.ladybug-tech.com

5



← Click Next

6




← Check Both for Pulse Profiling

← Otherwise Check Power Meter


← Check High Speed Logger and/or Sample Code if desired

7





← Click Next

8




← Click Next

9



Click Close

10



Connect Sensor


11



← Select

← Click Next

12



Click Finish

Installation Complete.
Begin Making Power Measurements ...

